



FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle **FIELD REPORT NO.:** ThirtyTwo (32)

**CONTRACT:** Construction Management @ risk **ARCHITECTS**  
HG Reynolds **PROJECT NO.:**

---

**DEFICEINT WORK:**

None

**PHOTOS:** Attached



Brick Veneer with flashing consistent @ Areas C & D

FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle **FIELD REPORT NO.:** ThirtyTwo (32)

**CONTRACT:** Construction Management @ risk **ARCHITECTS**  
HG Reynolds **PROJECT NO.:**

---

FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle **FIELD REPORT NO.:** ThirtyTwo (32)

**CONTRACT:** Construction Management @ risk **ARCHITECTS**  
HG Reynolds **PROJECT NO.:**

---

FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle **FIELD REPORT NO.:** ThirtyTwo (32)

**CONTRACT:** Construction Management @ risk **ARCHITECTS**  
HG Reynolds **PROJECT NO.:**