

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Thirty One (31)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**


INSPECTIONS:

1) CSRA tested welding of steel and bolt connections.

DEFICEINT WORK:

Correction to CSRA Steele Report No. T-16-U63

PHOTOS: Attached



Joist - Area D


FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Thirty One (31)

CONTRACT: Construction Management @ risk
HG Reynolds

ARCHITECTS
PROJECT NO.:




Metal Decking Area B

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Thirty One (31)

CONTRACT: Construction Management @ risk **ARCHITECTS**
PROJECT NO.:



Prep of Metal Deck Area A for placement

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Thirty One (31)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**

Prep of

FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Thirty One (31)

CONTRACT: Construction Management @ risk
HG Reynolds

ARCHITECTS
PROJECT NO.:



Damper beneath flashing Area D

McMILLAN PAZDAN SMITH