

McMILLAN PAZDAN SMITH

FIELD REPORT

WCI GROUP LLC

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty Nine (29)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**

INSPECTIONS:

1) CSRA tested welding of steel and bolt connections.

DEFICEINT WORK:

N/A

PHOTOS: Attached

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty Nine (29)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**

1st floor slab C wing

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty Nine (29)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**

cable tray and fire alarm conduit installation c wing

FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Twenty Nine (29)

CONTRACT: Construction Management @ risk
HG Reynolds

ARCHITECTS
PROJECT NO.:



plumbing rough in D wing



FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty Nine (29)

CONTRACT: Constructio3o5(b)-5(b(96R82)-5b)-5

FIELD REPORT

PROJECT: Leavelle McCampbell Middle


FIELD REPORT NO.: Twenty Nine (29)

CONTRACT: Construction Management @ risk

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty Nine (29)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**



clean up throughout

McMILLAN PAZDAN SMITH

FIELD REPORT

WCI GROUP LLC

4R12TJTJET00000912 0 612 792 reW*hBT

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty Nine (29)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**



scaffold removal A wing & C wing

Report by: Bill Williams